

0523359

0053790

## Waste Site Reclassification Form

<b>Date Submitted:</b> 3/24/2000	<b>Operable Unit(s):</b> 200-LW-2	<b>Control Number:</b> 2000-018
<b>Originator:</b> J. W. Golden	<b>Waste Site ID:</b> 200-W-46	
<b>Phone:</b> 376-6961	<b>Type of Reclassification Action:</b>	
	<input checked="" type="radio"/> Rejected <input type="radio"/> Closed-Out <input type="radio"/> No Action	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**

The site is a Satellite Accumulation Area for Room 4E of the 222-S Analytical Laboratory.

**RECEIVED**  
 OCT 03 2000  
**EDMC**

**Basis for reclassification:**

Active satellite accumulation areas are intended to provide interim generator storage for waste prior to treatment, storage or disposal of the waste. Per the requirements for Solid Waste Management Units found in TPA-MP-14 and the definition in WAC 173-303-040 for satellite accumulation, this does not fit the definition of a SWMU for inclusion in WIDS.

This active SAA is managed according to the requirements found in WAC 173-303-200(2), Satellite Accumulation. Satellite accumulation of waste typically occurs near the point of generation, in containers equal to or less than 55 gallons, and is removed when the activity is complete. Any spills from an SAA are cleaned up and managed appropriately; hence, SAAs do not routinely or systematically release waste to the environment, and do not require corrective action.

Per the TPA-MP-14, 90 day storage areas and satellite accumulation areas are maintained on a separate list as documented in the operating record per Condition III.1.1.a of the Hanford Facility Wide RCRA Permit. The site is listed as a Satellite Accumulation Area on the "PHMC SAA Inventory Report."

<u>Steve Burnum</u>	<u>Steve Burnum</u>	<u>8/23/2000</u>
DOE Project Manager	Signature	Date
<u>Wayne Super</u>	<u>Wayne Super</u>	<u>9-6-00</u>
Ecology Project Manager	Signature	Date
<u>Doug Sherwood</u>	<u>Doug Sherwood</u>	<u>9/14/00</u>
EPA Project Manager	Signature	Date